

LO (Continued)

24th January, 1956.

all "ESSO 5" As recommended. It is concluded that it was the
at main engine crankshaft which was renewed at this time, not
the engine itself, as stated by you. Please confirm that the
electrical installation has now been placed in order (Your Report
7788 refers).

It is noted that a number of survey reports which were
before the Committee at this time were for surveys carried out in
October and November last, and I would draw your attention to the
terms of Circular No. 2001 in this respect.



© 2021

Lloyd's Register
Foundation

013042-013051-0037