

24th March, 1959.

Two

PRIMSBY

27795, 96, 99, 800, 04, 08 - As recommended.

"GELOW" 27787 - As recommended, except that the notation ES 2.59 has been assigned.

27786 "SARDINIAN" - As recommended, except that a definite date for the screwshaft renewal should be given, and I shall be glad to receive your recommendation in this respect.

It is noted that a spare (previously used) screwshaft, which was found in good order, has now been fitted. From the records in this Office, however, the shaft now removed, which was fitted new in January, 1947, was to replace a shaft stated to be deeply corroded at the top of the cone. This is not consistent with the statement above, and I shall be glad to receive your comments on this point.

You should also obtain from the Owners some information regarding the origin of this shaft.

In the survey records table at the top of your rpt. 9 notation of "O.G." is shown, whereas your recommendation is "C.L." and I shall be glad if you will clarify this matter.



© 2021

Lloyd's Register
Foundation

013042-013051-0121