

COPY

Ship's name

ELLIOT

Port

Sea

No.

5412

Last survey date

17.2.64.

GB

Class is subject to

shell plate D.2 (p.s) in way of tunnel
bilge well and F.14 (p.s) in way of No.1 hold also F.14
(s.s) being specially examined and dealt with as necessary
next drydocking.

S.R.L. Appendix (as before or none) x

Nature of present survey (afloat and in drydock)

Docking: Deferred repairs to H.W. damage.

Recommendation:

NOTED.


DS 2,64 Subject as above, and to set in
shell plating and framing in way of
2nd, 3rd 4th & 5th strakes below sheer (p.s)
etc. being specially examined and dealt
with as necessary by S, 64.

DS 2,64 Subject

IN S.R.L. APPENDIX.

(Outer plate (p.s) E.W. 9,60)

It is concluded the Surveyors were in error in
reporting 17 lengths of c.c. on board instead of 15
required by equipment letter "at" but confirmation is required.



© 2021

Lloyd's Register
Foundation