

MARE ADRIACUM

The repairs carried out at Genoa as given in Rpt. 22976 have been noted and appear to be efficient.

It is thought the reported fractured were due to propeller excited vibration.



The vessel was investigated for vibration on the 10th September 1956 and a five bladed propeller recommended. This propeller has now been fitted and future trouble of this nature ~~is not anticipated.~~

*will not occur*

*it is hoped that*

*JA.*

19th June, 1958.



© 2021

Lloyd's Register  
Foundation

013186-013191-0096