

SHIP'S NAME

"MONSUN"

PORT

HFS

No.

1696

APPDX....M

LAST SURVEY DATE

24.5.66.

CLASS IS SUBJECT TO

Repairs to welds of stiffening plates between M./E. frames No. 8 & 9 F & A & No.6 A. Port side (E.W. 6.64) being specially examined by 6.66. (12 months).

2. P.F. end of M.E. "A" frame plating at centre of engine in way of chain drive casing repair (9.65) being specially examined by 3.67.

Subject Item 1 :- Stiffening plates throughout examined & cracks found. The Surveyor now recommends the main engine "A" frame stiffening plates between units Nos. 5 fwd. & aft., No 6 fwd., No 7 fwd., Nos. 8 and 9 fwd. & aft. be specially examined & dealt with on the ship's arrival at Hamburg & before the end of 6/66.

C.S. Advanced.

It is submitted that this vessel is eligible to remain

as **CLASSED**. subject as above for Item 2 and as now amended and recommended for Item 1.

JTB
9.6.66.

SRH Appendix

Amend: DBS to ABS



© 2021

Lloyd's Register
Foundation

AR Ham 5/6