

"TEBRO" ex "BARON MACLAY"

In reply to their letter of 6.8.57
enclosing copy of Owners' letter of 2.8.57
SUBMITTED the CARDIFF Surveyors be advised as
follows:-

- (a) Shell plating was drilled in accordance
with B.C. Rules in 1953 (i.e. for a period
of four years) and necessary repairs were
effected to cover that period.

Under the Unified Rules the shell and
deck plating will require to be drilled
at the Special Survey (due 8.57) which
will cover a period of 12 years.

- (b) Copy of Mch. Rpt. ⁹No. 17539 should be
furnished as requested.

J.H.B.
9.8.57.

R
9/8/57



© 2021

Lloyd's Register
Foundation

013325-013338-0425

[Signature]
Surveyor