

Received from Chief Ship Surveyor

3 JUL 10

P'S NAME "BARON MACLAY"

REPORT Mdb.

No. 20989

Standing Conditions of Class:

Subject to the top of rudder post and outer plates (p & s) in way (E.W. & reinforced 11,56 & previously) being specially examined at the next drydocking, and to temporary repairs to side shell plate (p.s.) in way of after E.R.bulkhead being dealt with by the next Special Survey.

Alterment of Class (B) (~~As before~~ or None)

Location of Present Survey: (~~Afloat~~ and in dry dock)

Docking: Wear and tear repairs and to part of the deferred items as above.

Recommendation:

SUBMITTED NOTATION of 'DS 6,57' be assigned, subject to the top of the rudder post and outer plates (p & s) in way (E.W. & reinforced 11,56 & previously) being specially examined at the next drydocking, but without other condition.

DS 6,57 Subject Without.



© 2021

27.6.57

Lloyd's Register Foundation

013329-013338-0432

Blk(new)

"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

this ship so far as now surveyed