

Received from Chief Ship Surveyor..... **5 SEP 1961**

SHIPS NAME "TEN HU" REPORT H.Kg. No. 16421  
GB

Outstanding Conditions of Class: SUBJECT to bottom plate A.5 (s.s. from fwd)  
(temporarily repaired) in way of coal bunker being specially  
examined and dealt with as necessary at the Special Survey.

S.R.L. Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Repairs to steering gear.

Recommendation: SUBJECT as above.

As Now. Subject

IN S.R.L. APPENDIX.

(Shell and deck plating to be drilled  
to Rule requirements next Special Survey (due 12,61))

IT IS FURTHER SUBMITTED the Surveyors be advised it  
is concluded the lengths of chain replaced at this time have been  
tested in accordance with Rule requirements.

