

COPY.

ENGINEER

COPENHAGEN

(28.10.38.)

HOEGH SILVERSTAR REFERRING YOUR CABLEGRAM VANCOUVER SURVEYOR REPORTED AUGUST 18
NUMEROUS SURFACE CRACKS AND CORROSION IN STERNFRAME THESE REPAIRED BY ELECTRIC
WELDING AND SURVEYOR RECOMMENDED LOWER HALF FURTHER EXAMINED OR RENEWED NEXT DR
DOCKING STOP NO FURTHER REPORT RECEIVED STOP VESSEL WITHDRAWN FROM CLASS 29TH U
COMMITTEE



© 2021

Lloyd's Register
Foundation

013436-013443-0195