

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

SSEL'S NAME

"HOEGH SILVERSTAR"

Rpt.

Vcr. No. 4870

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel was built in January, 1938.

The Vancouver Surveyor has now reported the vessel examined in dry dock in August last, some riveting etc. dealt with and minor repairs carried out.

The rudder~~post~~ of the sternframe found to have numerous surface cracks/^{has been} repaired by electric welding and reinforced with a steel plate, and the upper joint between the top and bottom castings has been similarly reinforced.


The riveted connections of the boundary plating of the after deep tank, port and starboard, which was classed to carry vegetable oil, has been reinforced by electric welding to enable this tank to carry oil fuel.

This was done on the Owner's instructions in accordance with plans furnished by him.

With regard to these arrangements reference should be made to the special endorsement dated 23rd August last.

The Surveyor, at the same time, wrote that the vessel had been surveyed by the Norske Veritas with a view to classification.

The attached letter has now been received from the Oslo Surveyors confirming that the vessel has now been transferred to the Norske Veritas, and some reasons for this decision are indicated. (See also endorsement dated 19th instant).





© 2021

Lloyd's Register
Foundation P.T.O.

(2)


"HOEGH SILVERSTAR"

It is submitted the class of this vessel
be withdrawn from the Register Book and Three Dots (...) 
inserted in lieu thereof, indicating withdrawal of class
at Owners' request. 

20. 9. 38

Withdraw class

Insert (...)



© 2021

Lloyd's Register
Foundation