

DISCLOSED SECTION No. 667

DISCLOSED SECTION No. 667

(Received at London Office)

Lon No. 128868 A

REPORT OF SURVEY FOR REPAIRS, &c.

No. in Reg. Book 19241 Survey held at on the Wood, Iron or Steel Date, 1917 First Survey 1917 Last Survey 1917 Port of Gothenburg

TONNAGE: GROSS 1554 UNDER DK. 1277 NET 808 Built at OSKARSHAMN By whom OSKRSHMNS M.V. AKTIES Owners Rederiaktieb Svenska Lloyd Managers K. R. Bökman Owners' Address Gothenburg

Surveyed Afloat or in Dry Dock? in Dry Dock Name of Dock in cell Particulars of Classification (which must be inserted precisely as in Register Book & Supplements):

+100A1 Shelter deck with freeboard 12.53 SS. Got 2nd No. 3. 7, 43. SS. SOG 11, 50. + LMC 11, 50 BS 12, 53 15 OG 10.52

Periodical Surveys, when held must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

REPAIRS, OR EXAMINATION AS PER RULE FOR Was a damage report made by anyone else? if so, by whom?

Summary of Damage Repairs :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed, ...								
Removed and Faired or Repaired								
Faired or Repaired in place								

SENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Condition of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Fastenings	Cement or Asphalt	Oil Bunkers	Boats
Plating	Rudder	Scuppers	Masts, Yards, &c.
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
Frames	Windlass	Hatches	Equipment letter
Radicals	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Recesses	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
ns.	Have Watertight Doors been examined and found efficient?	Treenails	length mean diam. (on board.)
rs.	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
the Tanks been examined internally?	Doubling Plates, under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
the Tanks been tested?		" " at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Salting (State if examined)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Traveling Expenses (if chargeable)	£	:	:	Received by me,
and Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRIDAY 7 MAY 1917 Character Assigned Withdraw class Write down 2 used (...) 2011 - Delete present Owners from R.B.

Surveyor to Lloyd's Register of Shipping. GENERAL COMMITTEE Thursday, 20th May 1917. Classing Committee's decision confirmed. R.A.P.

013489-013496-0211

Is Certificate required? If so, to be sent to