


for foreseeable breakead door openings does
not agree with the "As fitted" plans,
and they should be requested to state
whether the stiffeners are $2\frac{1}{2} \times 2$ " or $2\frac{1}{2} \times 2\frac{1}{2}$ "
and whether the door sill is 24" or 27"

Geo. 2/18/63


201

© 2021

Lloyd's Register
Foundation

013447-013507-0147

ous protective devices were adjusted and operated. The insulation

11
sta

C.11

~~Freeboard~~ Report on ... "ATLANTIC DOLPHIN"

Report C11 examined for compliance with the
Society's Rules for Trawlers and approved
plans, and found to be in order.

The Surveyors should be
informed that the information given
on Report C11 for precast bulkhead
stiffeners and height of door sill

© 2021
Lloyd's Register
Foundation