

013750-013759-0215

~~013759~~

Ship's name "PRODOS"

Port

Rot

20 MAY 1965

No.

60184

Last survey date

2.10.64

Class is subject to leakage at E.R. bilge (s.s) also to hawse pipes (temporarily repaired) and indented shell plates etc K.10 and J.9 (s.s) and to the rudder and rudder stock (twisted 50°) and steering gear being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for examination in drydock after grounding.

S.R.L. Appendix (xxxxxxxxxxxxxx none)

Nature of present survey (afloat and in drydock)

Docking. Damages (fire, grounding & cause not stated) - no repairs effected under L.R. survet.

Recommendation

SUBMITTED record of 'DS 10,64' be assigned, subject as above, and to indented shell plating (p&s), deck and bulkheads in way of Nos.2 & 2A tween decks being specially examined and dealt with as necessary next drydocking.

bottom & side


DS 10,64 Subject  
DELETE FROM S.R.L.

Drydocking (grounding).

NOTE:- It is noted notation "CLASS WITHDRAWN -REPORTED DEFECTS" was assigned 26.2.65.

It is also reported that certain repairs have been carried out under B.V. survey and the ship is now classed with B.V.

5/5/65



© 2021

Lloyd's Register Foundation

C.S.S. Records Dept.  
to note.