

Rpt. 8

7/ H.K.M

Port

Oslo.

16 001 9417

Date of writing Report 13/11/61

When handed in at Local Office

Received London

Survey held at Drammen

No. of Visits 1

First Date and 19

Last Date 21/6 1961

## REPORT OF SHIP SURVEYS AND REPAIRS

(The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. 838 C

22163

on the Iron or Steel S.S.

" STAB VIII "

Built at Middlesbrough

By Whom Smith's Dock Co. Ltd.,

When

Tons gross 413  
Year 1948 Month 10

Owners Hvalfangerselskapet Rosshavet A/S

Owners' address  
(If not already in R.B.)

Managers Johan Rasmussen & Co.

Port of Registry

Surveyed Afloat or in Dock

Floating dock

Name of Dock

Drammen Slip & Verksted

Date of last examn. in

Floating dock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No. 9150  
To be filled in at Head Office.

Port

OSL.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
BS +	MBS +
whaling purposes	ES 10/60
	MBS 8/60
SS 10/60	TS(CL) 6/60
DS 7/60	SPS 11/55

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified ft ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR Docking Survey.

A number of minor wear and tear repairs effected.

DISCLOSED  
SECTION

No. 838 C

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								

Has a Survey also been held on machinery of the Ship? Yes

Is Classification Certificate required? If so, to be sent to

If so, is the Report sent now, or when will it be sent? Now

Has Interim Certificate been issued?

Yes, copy attached.

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:— "to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

This ship, so far as now seen, is in good condition and in my opinion eligible to remain as classed with fresh record of DS 6/61.

Surveyor to Lloyd's Register of Shipping

P.L.Vaaheim

Date of Committee

TUESDAY - 5 DEC 1961

Minute

DS 6 61

MBS 8 61

50m,4,59 T. (MADE AND PRINTED IN ENGLAND)



© 2021

Lloyd's Register  
Foundation

013750-013759-0251



PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR

## SURVEY

Have the spaces now surveyed been cleared and cleaned as necessary? Yes

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? No

Have the bilges been cleaned out and examined? No Has cement in bottom been examined? No

Has steelwork had rust removed and afterwards been recoated as necessary? Yes

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? No

Has a Load Line Survey been held? No If so, state which -

Have the shell and deck plating been drilled as per Rule? No If so, Report 8(Dr) to be attached -

Have any alterations to the approved scantlings and arrangements now been effected? No If so, report details in body of Report.

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word "Yes", e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? None See Below

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee ..... Kr. 100.-

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable) Kr. 50.-

Second Surveyor's Fee (if any)

Date when A/c. Rendered

Date when A/c. Rendered 13/11/61

© 2021

Surveyor's Fee (if any) .....  
When A/c. Rendered ..... 13/11/61