

198 JAN 1967

Kang Kora R28 Z0618

SHIP'S NAME

BALI MARINER

PORT

KOB

52

No.

60

LAST SURVEY DATE

19-11-66

CLASS IS SUBJECT TO

- 1 M/L REPAIRS 5/66 TO P. LP & HP BLAST INJECTION AIR COMP^R
COOLER CASINGS BEING EXAMINED BY 10/66 (6 mos)
- 2 S. M/E N°3 GUIDE FACE (M/L 3.65) BEING EXAMINED
BY 9.66 (12 mos)

SUBJECT ITEMS 1 & 2 EXAMINED FOUND EFFICIENT TO DUTY

DOCKING. (WD, P. 1185"
S 113")

ABS DNR. 3 66 H&SD

SURVEYOR REPORTS THAT M/E ATTACHED BILGE PUMPS HAVE BEEN
DISCONNECTED SINCE 1959, & ARE IN BAD CONDITION, & RECOMMENDS
PORT & STARBOARD M/E DRIVEN BILGE PUMPS TO BE REPAIRED OR
RENEWED BY 4.67 (6 mos)

INSERT IN SRL APPROX

PORT M/E HP/LP BLAST INJECTION
AIR COOLER FLANGE M/L 5.66

STARBOARD M/E N°3 GUIDE FACE

M/L 3/65

C.S. Advanced.

It is submitted that this
material is eligible to remain


~~CLASSIFIED~~ WITH REPLY

ABS 10-66 WITHOUT SUBJECT
ABOVE BUT AS NOW RECOMMENDED

ALSO SUBMITTED POST? S-3

MEANS APPROVAL

CONTINUED



© 2021

Lloyd's Register
Foundation

014077-014082-0068