

EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN
AUXILIARY
(over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY
Total kW or kVA		Total kW or kVA
a Generators		l Generators & governors
b Exciters		
c Air coolers		m Motors
d Motors		
e Air coolers		n Switchboards & fittings
f Control gear cables, etc.		o Circuit breakers
g Insulation resistance		p Cables
h Insulating oil test		q Insulation resistance
i Overspeed governors		r Steering gear generators & motors
j Magnetic couplings		s Navigation light indicators
k Air gap		

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.


DAMAGE.

Damage stated to have been caused by the starboard propeller striking an unknown object off Waterloo Lock, Liverpool on the 19.7.64

DAMAGE REPAIRS.

Starboard propeller (3 blades) - all blades found badly bent.
Spare bronze propeller now fitted.
Oil gland examined and found satisfactory.
Tail shaft turned in place and gauged for truth and found satisfactory.
Fit of tail shaft in new propeller verified and found in order.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Lloyd's Register
Foundation