

...n easily accessible mud-boxes, placed above the level of the working floor, with straight tail pipes to the bilges

Regine
S.L.
Huller No. 5-0335-6 Made by Loc. Exp. de Constr. Lomas


r. Lw. Lc. M.S. Campeche

Blo Report No. 8393

a copy of
It is submitted that this Report be returned to
the *Cadiz* Surveyors for their guidance and
for completion.

Date

17/1/34



014287-014299-0233

© 2021

Lloyd's Register

Foundation

...ss, lap welded or riveted longitudinal joint

riveted

Material

S.M. steel

Range of tensile strength

41-47 kg

Working pressure

For Mr Cook



© 2021

Lloyd's Register
Foundation