

This vessel is laid up pending survey.

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME MONTEREY ..... S.Fo. 9507  
REPORT..... No.....

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Survey..... Damage. .... When due..... --

NOTED

Shell plating, etc. in way of No. 10 port oil fuel tank required to be repaired before the vessel resumes trading.

IN S/R.L:

Aluminium deckhouse on sun deck to be specially examined and reported upon at every drydocking.

Laid up pending survey.



© 2021

*JSA*  
20450

Lloyd's Register  
Foundation

014513-014530-0039