

Stl. Sc. "TOTARA"

Hul 36940.

An electric light installation has been fitted in this vessel at Hull.

In their report the Hull Surveyors state that the navigation light indicators, which are required by the Rules for Electric Fittings, have not been fitted.

The omission was pointed out to the Contractors by the Surveyors who informed them that if the indicators were not fitted the Owners' consent should be obtained and the matter submitted for the consideration of the Committee. The Contractors are stated to have written to the Owners but no reply appears to have been received.

The Surveyors also pointed out the omission to the Owners' representative who raised no objection.

In steam trawlers and in some cases of tugs, the fitting of navigation light indicators has been dispensed with.

In the case of this vessel, which is about the size of a steam trawler, it is submitted the fitting of the indicators be dispensed with provided the Owners' consent be obtained.

L15/4/26

②



© 2021
13.4.26.

Lloyd's Register
Foundation

014513-014530-0346