

Rpt. 9B

REPORT OF MACHINERY SURVEYS AND REPAIRS  
FOR CONSIDERATION BY THE COMMITTEE OF LLOYD'S REGISTER OF SHIPPING

Received London

18. NOV. 1968

Ship's Name SS/MS " ACME "

Port Piraeus

Processing  
Number: LR 504329

Gross tons 7173

Rpt. No. 14364

Port of Registry

Date of  
build

Is there a rpt. 8?

No. of visits

First date

Last date

Interim Cert. Issued  
& copy herewith?Damage rpt. Issued  
& copy herewith?

Last rpt. (H. Q. only)

Date of  
completing rpt.

Surveyed at, if different from Port above

Is a rpt. 9A  
attached? Yes

MN

Nature of survey

Survey fees

Damage fee

Expenses

S.A. fee

BOILERS OPENED UP AND EXAMINED. (Identify by position and state condition and latest date of internal examination of each boiler, economiser or steam generator)

AUXILIARY, DONKEY or PRESS

(State if oil fired—OF  
or exhaust gas—EG)

MAIN Port 29.10.68 - Good

Air heaters

-

Superheaters

Good

Safety valves

Good

Mountings, doors  
and fastenings

Good

Safety valves  
adjusted to { Sat  
Spt240 lb/in<sup>2</sup> Port boiler only.230 lb/in<sup>2</sup> Port boiler only.Boiler securing  
arrangements

Good

Main economisers -

Exhaust gas heated economisers  
and their safety valves -Steam heated  
steam generators -Steam generator or  
E.G.E. safety valves adjusted to -Fired boiler forced  
circulating pumps -

Funnel -

Have saturated steam pipes in cylindrical boiler  
smoke boxes been examined as required by the Rules? -Were oil burning system &  
remote controls examined  
in accordance with Rules? Yes - Good

I declare that the items detailed in this report (except as stated otherwise) comply with the requirements of the Merchant Shipping (Cargo Ship Construction and Survey) Rules 1965, applicable to this ship, and are in all respects satisfactory for the service on which the ship is intended to ply, namely, International voyages/voyages within the limits

(The above declaration applies only to sea-going cargo ships  
of 500 tons gross and above registered in the U.K.)

I recommend that the machinery of this ship remain as classed with/without fresh record of

See Report 9 A.

(Where conditions of class are recommended to be  
retained, imposed, amended or deleted, particulars  
must be stated above and on the interim certificate.)

Date of Committee

Minute

See 9a.

J. Wood

Surveyor to Lloyd's Register of Shipping

ALSO FOR

SRL FOR

TRO

SRL

POSTING

HEADER

CERT

© 2021

Lloyd's Register  
Foundation

014675-014685-0049

are to be cancelled; this need not be done when the machinery is  
on a continuous survey basis. When any part has been hydraulic-  
ally tested the pressure should be stated. Engine parts when referred  
to by numbers should be counted from forward.that date a distinguishing mark must be inserted against the  
item and the circumstances and action taken or recommended  
described fully under "defects and repairs". At part or complete  
Special Surveys those items which are not applicable to the shipThe condition of any item is to be described as "good" only when  
it has been examined, found or placed in good condition, and is  
considered to be acceptable until the due date of the next Periodical  
Examination. Where re-examination or repairs should be made before



EXAMINATION AND TESTING OF STEAM PIPES (state material and test pressure and, if selected lengths, identify by position)

MAIN

AUXILIARY  
(over 3" bore)

Have saturated pipes in cylindrical boiler  
smoke boxes been tested?

Were selected copper pipes annealed?

ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a	Generators	l	Generators & governors
b	Exciters		
c	Air coolers	m	Motors
d	Motors		
e	Air coolers	n	Switchboards & fittings
f	Control gear cables, etc.	o	Circuit breakers
g	Insulation resistance	p	Cables
h	Insulating oil test	q	Insulation resistance
i	Overspeed governors	r	Steering gear generators & motors
j	Magnetic couplings	s	Navigation light Indicators
k	Air gap		
t	Spare gear		

u PASSENGER SHIPS Have the emergency source of power and its associated circuits and, where fitted,  
the temporary source of power and its automatic arrangements been tested?

CARGO SHIPS Have the emergency source of power and its associated circuits been tested?

PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

Main Boiler Survey commenced with the examination of the Port Boiler.

Minor wear and tear repairs effected to mountings.


To complete the survey : The starboard boiler remains to be examined in its entirety and its safety valves adjusted to the working pressure.

The vessel is now proceeding to Malta to dry dock and it was stated that the survey would be completed at that port.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept, the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.

State whether continuation sheet attached

No.



© 2021

International Register  
Foundation