

m.s. "ISLE OF SILHOUETTE"

IT IS SUBMITTED the New York Surveyors in answer to their cablegram dated 19.4.55 be advised that before the class of this ship can be reinstated in the Register Book as formerly, it will be necessary for:-

1. The requirements of a Restoration Survey to be complied with.
2. Any major repairs which have been effected to the structure since the ship was disclassified to be specially examined in order to ascertain the character of the workmanship and confirm that the materials used are in accordance with the Rules.
3. Structural alterations which may have been carried out since the ship's class lapsed and which affect the longitudinal and/or transverse strength of the ship to be reported.
4. Full particulars of the equipment on board, including weights, tests, etc. of anchors and tests, etc. of chain cable to be furnished, and
5. the survey to be carried out by a Surveyor who if not specially qualified in wood construction should be joined by an approved wood expert.

IT IS ALSO SUBMITTED a photostat copy of the Mombasa Rpt.No.703 be forwarded to the Surveyors for their information.

Submitted N. Yk. Surveyors be informed
that in view of ship's present condition
as reported, re-class is not considered
a practicable proposition but if owners
so desire reclass the above are our reqs.

ABM
19.4.55.

© 2021

Lloyd's Register
Foundation

014984-014995-2044