

Surveyor

Received from Chief Ship Surveyor

27 AUG 1954

"ISTE OF SILHOUETTE"

REPORT

Mba. No. 703.

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

ent to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

The class is subject to the ship's hog being recorded and reported upon at each drydocking.

ACTION and NOTATION of "H.T. Mba. '53" be DEFERRED until the foremast is renewed or dealt with as necessary before trading.

The MOMBASA Surveyor reports (8,54), ship examined afloat and on slipway for condition.

From the examination of the underwater structure on the slipway it was found that marine termites had infected the stem bar, sternframe and various parts of the shell planking, and on account of this major renewals are considered necessary.

The Owners ~~with~~ <sup>the</sup> ship ~~is~~ <sup>are</sup> still in dispute, and the Surveyor's recommendation to strip hold insulation internally ~~in~~ <sup>on</sup> account of severe straining was not agreed to, and in view of this, and the ship's condition as now reported, he recommends that the ship's class be expunged from the Register Book, which is submitted for the consideration of the Committee, refer also to the Mombasa Surveyor's letter dated 13.8.54.

Ly 23  
8  
54.

23.8.54.



© 2021

Lloyd's Register  
Foundation

0149847-014995-0048