

DISCLOSED

(Received at London Office)

Lon No. 128900

REPORT OF SURVEY FOR REPAIRS, &c.

No. of writing Report 19... When handed in at Local Office 19... Port of

No. in Reg. Book 14557 on the Wood, Iron or Steel S.S. JANE LANGG Date, First Survey Last Survey 19

TONNAGE: GROSS 2725 UNDER DK. NET 1557 Built at Belfast By whom Workman Blank & Co. When 1921 - 7

Owners DIS 'ACTIV' A/S. Managers L.R. SCHMITH & Co. Owners' Address

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell/Dor/DBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Only alterations in the existing records of tanks should be inserted.

N.B. All alterations in the existing records should be underlined.

Last Report, No. 138692 Port Liv

CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys.

Machinery and Boiler Surveys (Including date of N.B., if any). BS* 11.53. S.S. N.Y.K. - 549 MBS* 5.49 BLRS 8.52 MSP 8.52 TSCL 8.52

FITTED FOR OIL FUEL

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

PRIMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed, ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Plating of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Stowings	Cement or Asphalt	Oil Bunkers	Boats
Rings & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Side Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Longitudinals	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Transverses	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Stowings	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Have the Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Have the Tanks been tested?		" " at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Saltine	

General Observations, Opinion as to Class, Recommendation, &c. :

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example :- "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Transfer Ink. (The Surveyors are requested not to write on or over this ink.)

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRIDAY 9 JUL 1954

Character Assigned Henrik Cpm

GENERAL COMMITTEE Thursday 29th July 1954 Classing Committee's decision confirmed.

Lloyd's Register Foundation

015054-015062-0075

