

Rpt. 8.

## REPORT OF SURVEY FOR REPAIRS, &amp;c.

Date of writing Report

When handed in at Local Office

(Received at London Office)

Hon No. 128870

No. in  
Reg. Book

Survey held at

Date

First Survey

Port of

London

Last Survey

19

14/35 on the Wood, Iron or Steel

TS. ITAIMBÉ

(No. of Visits)

TONNAGE

Built at

St Nazaire

By whom

Chr Atal de St Nazaire

YEAR

1927

MONTH

3

GROSS

4993

Owners

Cia Nacional de Nav Costeiras

Address

UNDER DEK

3479

NET

2961

Machinery

(Patrimonio Nacional)

Port belonging to

Rio de Janeiro

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

Cell DB or DBa

feet

uE&amp;B

feet

feet

feet

total capacity

tons. FPT

tons

APT

tons

MT

feet

tons

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 5767.

Port Rio

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER.  
\* for Special Survey.  
Date of last Survey and of  
Periodical Surveys.Machinery and Boiler  
Surveys  
(including date of N.B., if any).

+100A-

with f.b.d

10.52

+LMC 10.52

TSOG 10.52

SS Rio 1.48 (DR)

SS Rio 10.52

Fitted for o.p. 3.27 15.12.1501  
DRY DOCKING OVERDUESociety's Freeboard (if assigned) as  
painted on Ship and now verified

In the cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

## SUMMARY OF DAMAGE REPAIRS:—

Shell Plates.

Frames.

R. Frames.

Floors and  
Bracket Floors.

Beams.

Inner Bottom  
Plates.

Dk. Plates.

Other Items:—

Renewed

Removed and Fair'd or Repaired

Fair'd or Repaired in place

## PRESENT CONDITION OF THE

Decks

Caulking of Decks

Coamings

Beams &amp; Fastenings

Outside Plating

in way of sidelights

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Plating

Have the Tanks been examined internally?

Have the Tanks been tested?

Bulkheads

Ceiling

Cement or Asphalt

Rudder

Steering gear and its connections

Windlass

Have pumps been examined and found  
efficient?Have Sluice Valves been examined and found  
efficient?Have Watertight Doors been examined and  
found efficient?Have Ventilators and their Coamings been  
examined and found efficient?

Air and Sounding Pipes

Doubling Plates under Sounding Pipes

Engine Room Skylights

Coal Bunkers, Openings, Covers, &amp;c.

Oil Bunkers

Scuppers

Cargo Hatchways

Hatches

Planking

Caulking

Treenails

Breasthooks &amp; Stemson

Transoms, Pointers &amp; Crutches

Timbers of Frame at openings

at other places

Stringers, Clamps &amp; Shelves

Salting

State if examined

Copper, or Y.M.

(State if on Felt.)

When fitted, Month

Year

Boats

Masts, Yards, &amp;c.

Condition, how ascertained

(State if wedges removed.)

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length mean diamr.

(on board.)

Rule length size

Chain Locker

Hawsers &amp; Warps

Standing and Running Rigging

Sails

## General Observations, Opinion as to Class, Recommendation, &amp;c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.38," or "to remain as classed and to have record of survey, 1.38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)

£

:

:

Fees applied for,

Special Damage or Repair Fee (if any)  
(per Sec. 23)

£

:

:

19

Travelling Expenses (if chargeable)

£

:

:

Received by me,

19

Second Surveyor's Fee (if any)

£

:

:

Committee's Minute

Character Assigned

GENERAL COMMITTEE

Thursday

20<sup>th</sup> May 1950Classing Committee's  
decision confirmed

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register  
Foundation

015102-015110-0053

Have Survey also been held on the Machinery of the Ship?  
If so, is the Report sent now, or when will it be sent?(MADE AND PRINTED IN ENGLAND.)  
20m.562 Transfer fol.  
(The Surveyor is requested not to write on or below the space for Committee's Minutes.)

Is Certificate required? If so, to be sent to