

Reyours

Received from Chief Surveyors

ME Steel 25. "POLJANA"

Report Als.
Ark.

No. 40157
17673

For the CHIEF SHIP SURVEYOR

See which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

When due

* 100 A. 1. (steel) "Skeller Dk. with freeboard"

1 Dk. (steel) & Skeller Dk. (steel).

Cell DB. 313' 1076h

MT 23' 721t.

FPT 92t. APT 88t.

FK. Collision BH to Skeller Dk. GBH to Upper Dk. pl. cent. Lloyd's AICP.

F 33' on Skeller Dk.

[Signature]

als.
12-7-20

The Surveyors should be requested to state whether the dry tank under has been tested & if so the length of the tank should be given.

in Ltr
13/8/20

015183- 015187- 0398

Lloyd's Register
Foundation