

image cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined

Yes

Not required

For service U.R. 72  
Coast, Channel Islands

Drakelow

Hull 59594

Before this case receives consideration  
IT IS SUBMITTED the Surveyors be requested to state  
whether the lubricating oil pump has been examined  
& the Port M.E. lubricating oil system cleaned as  
recommended by Gns. Surveyors.

They should also be informed that the metal  
spraying of rubbing surfaces is not a repair  
regarded favourably by the Committee &  
asked for their comments regarding the repair  
to the Sea and engine crankshaft.

Cf L's Hull Re

1519

189  
9. 9. 53

the insulation resistance of the generators, circuits and apparatus been tested and found to be not less than 100,000 ohms? ✓