



Tw.Sc. M.V. "DRAKELOW"

Continued:-

and the lubricating oil system on the port engine be thoroughly cleaned out. Owners advised by Ltr.4, copy attached.

*G.B. Dux*



© 2021

Lloyd's Register  
Foundation