

Received from Chief Ship Surveyor

9- JAN 1953

SHIP'S NAME 'DRAKELOW'

REPORT

Nwc.

No. 110055

Outstanding Conditions of Class:

Subject to indented shell plating (s.s.) abreast No. 1 hatchway being examined and dealt with as necessary at the next drydocking, and to adequate ventilation being provided to Engine Room at the earliest opportunity.

Endorsement of Class (B) (~~As before or~~ None)

Nature of Present Survey:

(~~Afloat and in dry dock~~)

Leakage in forward hold - temporary repairs.

See also Owner's letter dated 5-1-53.

Recommendation:

SUBJECT as above, and to defective shell stringer riveting (p.s.f.) in forward hold being examined and dealt with as necessary next drydocking.

As Now. Subject.



© 2021

Lloyd's Register
Foundation

015224-015232-0336

Frames in way of strength

Have pumps been examined and found eff-

Y.M. on h
d, M
da, &