

of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 9(Dr).

SS Bal.

7-54

CL

6-5

7-5

ams: Nymdible, New York

Telephone: Whitehall 4-0220
4-0221
4-0222
4-0223




LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

17 Battery Place,

New York 4, N. Y.

May 15, 1958



Dear Sir:

S.S. "SINCLAIR H.C."

Referring to your inquiry to the Philadelphia Surveyors regarding this vessel, the Owners advise that she is now laid up indefinitely at the Sun Yard, Chester, Pa.

Yours faithfully,

Secretary to the American
Committee

The Secretary

LONDON.

cc: PHILADELPHIA



© 2021

Lloyd's Register
Foundation

015348-015354-0077

015348-015354-0078

CLASSIFICATION

H 100
H 100

Committee of the American

Committee of the American

They had not yet been informed of the results of the investigation.

"U. S. S. 'ALBATROSS' - P. 2"

Dear Sir:



© 2021

Lloyd's Register
Foundation

LOADS REGISTER OF SHIPPING

RECEIVED

NEW YORK & N. Y.

12 BATTERY PLACE

RECEIVED

RECEIVED

ADDRESS-

besides being
below. When
must be repou
or retested th
attached to it

Page
cc:

Lon

Inf

We

at

It

sha

arr

ins

We

Dear

NEW

The

Minute