

The class is subject to the donkey boiler not being used until repaired, also to steam dynamo being examined under working conditions.

4E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP'S NAME "RAMA RAJA" REPORT Cal. No. 15414


The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey ~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

S.R.L. Donkey boiler permanently repaired.

IT IS SUBMITTED the vessel is eligible to remain as classed, subject to steam dynamo being examined under working conditions, and without other special conditions.



© 2021

Lloyd's Register
Foundation

19.2.53.

015355-015365-0103