

13 FEB 1968

Ship's name "FATEHABAD" Port Krh No. 1782

Last survey date 10.1.68

Class is subject to For conditions of class see previous endorsement.

ACTION is DEFERRED for S.S. by 12,67.

S.R.L. Appendix (XXXXXXXXXXXX none)

Surveys due SPECIAL SURVEY (D) due 4,67. Postponement until 11,67 approved 14.11.67 after a satisfactory G.E. Further postponement until 4,68 approved 14.9.67 subject to examination of shell plating in way of E. & B. Room (s) and wasted shell plating in way of Nos.4 & 5 holds (s) (S.R.L.)

Nature of present survey (afloat XXXXXXXXXXXXXXX)

Examination of subject items: Supply of bower anchor(S.R.L.) Deferred repairs to contact damage.

Is interim certificate in order Yes/No/None

Items outstanding if any for SS

ALL ITEMS

TO NOTE		TRO
S. PLANS	S. RESEARCH	S. DEVELOP.
FREEBOARD	E. REPORTS	PUBS.

SS proposed to be completed by See Committee Minute.

Glenn
13.2.68

Recommendation

SUBJECT to indented shell plates (s) in 2nd, 3rd & 4th strakes below sheer and structure in way of E.R. and B.R. to fractured shell plate J.7 (s)(temp. repaired) and to wasted shell plating in No.4 hold (s.a) and No.5 hold (s.f) being specially examined and dealt with as necessary by 4,68, to shell plate H.18 (s) frs.144/148(doubler fitted) and set in bulwark plating (p.f) and superstructure (p.amids & aft) being specially examined and dealt with as necessary by the S.S. to doubled shell plating in No.1 hold (p.a) being specially examined and dealt with as necessary next drydocking also to spare bower anchor being verified (supplied 1,68) at the earliest opportunity, but ACTION is DEFERRED for S.S.

SUBJECT AMENDED

* and to indented shell plates and set in framing in way of Nos.2&4 holds(p) being specially examined & dealt with as necessary next drydocking

X P.T.O. X

10.1.68

For conditions of class see previous

class is subject to endorsement.

ACTION is DEFERRED for 3.3. by 1.67.

IT IS FURTHER SUBMITTED postponement of S.S. until 4.68 merits approval.

Further approved 14.11.67 after a satisfactory examination of shell plating in way of No. 2 B.Room (a) and No. 2 B.Room (s) (3.1.1.1.)

Examination of subject items: Supply of power anchor (3.1.1.1.)

Deferred repairs to contact damage.

Yes/No

is in the certificate in order

See Committee Minutes.

See Committee Minutes.

is proposed to be completed by

documentation

SUBJECT to indicated shell plates (a) in 2nd, 3rd & 4th staves below sheer and structure in way of B.R. and B.R. to fractured shell plate 1.7 (a) (temp. repaired) and to waste shell plating in No. 4 hold (a.1) and No. 5 hold (a.2) being specially examined and dealt with as necessary by 4.68, to shell plate H.18 (a) the 104/108 (double fitted) and set in bulwark plating (p.2) and superstructure (p.1) and set in being specially examined and dealt with as necessary by the 5.68 to double shell plating in No. 1 hold (p.1) being specially examined and dealt with as necessary next drydock also to spare power anchor being verified (applied 1.68) at the earliest opportunity; but ACTION is DEFERRED for 3.3.

and to indicated shell plates and set in framing in way of Nos. 2&4 holds (g) being specially examined & dealt with as necessary next drydock

