

# ANNUAL SURVEYS.

368  
369  
LH

No. <sup>234</sup>368 Survey held at Aberdeen Date 16<sup>th</sup> October 1857  
 on the Schooner Simrod Master James Marsh  
 Tonnage 144 Built at Bridport When built 1847  
 By whom built Richard Russell Owners A & W Phillips  
 Port belonging to Aberdeen Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. <sup>41 & 162 Port of Aberdeen, No 1022 Port of London, &</sup> 272 Port of Aberdeen 10<sup>th</sup> October 1856 Classed AT

The Surveyor is required to state the present Condition of the as far as can be seen

Decks	Breasthooks	Capstan <u>Winch</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, Has received no particular repairs only caulking and the  
as required by the Instructions, necessary overhaul in the rigging and sails.  
Wm Christie

Committee Minute 3 Dec 183

Character assigned A, 1

No. <sup>191</sup>369 Survey held at Aberdeen Date 16<sup>th</sup> October 1857  
 on the Schooner William Master John Henderson  
 Tonnage 87 Built at Aberdeen When built 1851  
 By whom built <sup>92 Dec</sup> William Rennie Owners Alexr Adam  
 Port belonging to Aberdeen Destined Voyage Sunderland  
 If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. <sup>7, 145 &</sup> 256 Port of Aberdeen 2<sup>d</sup> September 1856 Classed AT

The Surveyor is required to state the present Condition of the Condition as far as can be seen

Decks	Breasthooks	Capstan <u>Winch</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, Has received no particular repairs only caulking and the  
as required by the Instructions, necessary overhaul in the rigging and sails.  
Wm Christie

Committee Minute 3 Dec 183

Character assigned A, 1



© 2021

Lloyd's Register  
Foundation