

5958, Alm.
Screw shaft examined
and propeller renewed, on
account of damage by
striking the buoy.

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

It is submitted that
this vessel is eligible to
remain as **CLASSED**.

A.C.H.

22.12.98



© 2019
Lloyd's Register
Foundation

THE SUBVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.