

1851  
RS.  
L

W. H. C.

Port London

REPAIRS

Where the planks were taken out in the Stakes, and below the Hold beam Clamps, and at the Floor heads, The timbers and inner Surface of the outside Planking were found in a sound good state, also a number of treenails that were driven out for examination with the iron bolts, in very good Condition

10

Decks	<i>See</i>
Upper Deck Beams & Fastenings	<i>See</i>
Lower Deck Beams & Fastenings	<i>Bolts See</i>
Spirketting	<i>See</i>
Plank Shears	<i>See</i>
Waterways	<i>See</i>
Hatchway Comings	<i>See</i>
Breasthooks	<i>Goods</i>

Transoms	Good
Timbers of the Frame	do
Topsides	do
Wales	do
Counter	do
Plank and Treenails (Outside to the Water's Edge)	do
Rudder	do
Copper	newly run, do

Windlass Good  
Capstan do  
Pumps Metal do  
Masts, Yards, &c. do  
Sails Part new do  
Cables Chain do  
Anchors No. of 3 B<sup>rs</sup> 12 lb 2 Kedge  
Standing & Running Rigging on 2 B<sup>rs</sup> do

General Observations and Opinion, We now consider the Barque "Warrior" from the extensive repairs she has at present received, with the extra fastenings received on the bottom at Calcutta, to be stronger in all her fastenings than she was when new. The Spars standing and running rigging and all her other sea stores are in the best condition and that she is fit for the safe conveyance of dry and perishable cargoes to and from all parts of the world, and we recommend that the "Warrior" may be posted to the first destination of the first class. A 1. for 4 years.

The Amount of Fee.....£ 4 : 0 : 0 is received by me, -

Getzmitt's Minute 30th April 1844

Committee's Minute \_\_\_\_\_  
Character assigned \_\_\_\_\_  
Gentl Enclly 2 May 1844  
Hapd 7 1 Then Cont 2 2

Character assigned General 1844

Slaves 7  $\frac{5}{1}$  then Cent 2  $\frac{1}{2}$

Th.

Wm. Young

Chas. H. Lloyd's Register

A close-up photograph of the fore-edge of a book. The image shows the binding structure, including the spine and the edges of the pages. The pages appear aged and slightly discolored. The binding material is visible along the spine, showing a dark, textured surface. The overall appearance is that of an old, well-used volume.