



Her Masts, Yards, &c. are in Good condition, and sufficient in size and length.

2129 Abn

She has SAILS.

CABLES, &c.

ANCHORS, and their weights.

No.

Fathoms.

Inches.

No.

Weight.

2 Sails  
Fore Sails,  
Fore Top Sails,  
Fore Topmast Stay Sails,  
Main Sails,  
Main Top Sails,  
and all New.

Chain	Tested to 44 fms. at 12 ft to 18 fms.	300	1 ft
Hempen Stream Cable	.....	70	1
Hawser	.....	90	8
Towlines	.....	90	11
Warp	.....	90	5
All of good quality.			

Bower	Each Tested to 24 fms.	.....
Stream,	.....	.....
Kedge,	.....	.....
		24.2.9
		2.3.24

Her Standing and Running Rigging all new sufficient in size and good, in quality.

She has one Long Boat and 3 Tenders.

The present state of the Windlass is Good Capstan Good Rudder Good Pumps 2 good.

General Remarks and Statement and Date of Repairs, if any.

DATES of Surveys  
held while building,  
as per Section 35.

- 1st. When the Frame is completed  
2nd. When the Beams are put in, &c.  
3rd. { When completed, and before the  
plank be painted or paved

July 1<sup>st</sup> 1813.

May 8<sup>th</sup>

August 4<sup>th</sup> 1813.

This vessel is well built, with iron plates & wood  
skin for the twelve years past, with a permanent  
water tight roof. But not in accordance with rule for  
an additional period of another year, being only seven  
months building. She has obtained a water clock  
& gallant forecastle built in accordance with rule  
See 37/38. - On top plates on top of Noel 3<sup>rd</sup> thick by 2<sup>1/2</sup>  
inches, extending from upper part of fore deckwood  
to upper part of after deckwood, knee, bulkhead  
through the steel & garboard strakes, all four aft  
The floor plates & the heels of frames forward & aft  
are riveted to the said plates. The garboard  
strakes are longitudinally bolted to the steel  
beam other with 1 inch galvanized iron. Diagonal  
plates outside the frames, extending from the  
midship frames at the gunwale down to the  
fore & aft deckwoods, 1<sup>1/2</sup> by 2<sup>1/2</sup> riveted to each  
frame. Bilge keels, plates 9<sup>1/2</sup> by 2<sup>1/2</sup> in deep  
with double angle irons 9<sup>1/2</sup> by 5. Floor plates  
at bilge keels 4<sup>1/2</sup> deep, - Stringer plates at beam  
ends 3<sup>1/2</sup> by 2<sup>1/2</sup> inches, - & on each side of hatchways  
on top of beams 3<sup>1/2</sup> by 12<sup>1/2</sup> by 16 pair of diagonal plates  
3<sup>1/2</sup> by 4<sup>1/2</sup>, extending from bilge to steel beam. Strake  
plates at beam ends - and 18 pair of st. between  
dicks extending from upper to lower deck, thin  
iron riveted to both frames. The whole of the  
rivets used are in accordance with the rule,

Present condition of Caulking of Bottom, Good Deck, Good and Waterways Good,

If Sheathed, Doubled, Felted, or Coppered Peppermint When last done 1813.

I am of opinion this Vessel should be Clasped 12. A. I.

The Amount of the Fee £ 5. - is received by me

Special £ 37. 11.  
Fees received £ 42. 10.  
Certificate £ 42. 10.

Committee's Minute 15<sup>th</sup> September 1813

Character assigned A for 12 Years

Raise to 13 WT

Age (B.S) 87

Water surveys while building.  
Febt 2<sup>nd</sup> 1813.  
March 5<sup>th</sup> 1813.  
April 3, 7, 10, 21, 27, 28.  
May 2, 8, 15, 21, 26, 28.  
June 3, 13, 14, 19, 21.  
July 2, 9, 14, 21, 26, 28.  
Augt 1, 7, 11, 14, 21.  
Sept 2, 5, 12, 19, 26.

Lloyd's Register  
Foundation