

# Report of Survey for Repairs, &c., of Engines & Boilers.

(Received at London Office,

Received 17th December 1885.)

No. 3631

No. in Survey held at Dundee

Date, first Survey 26 Nov<sup>r</sup> Last Survey 2 Dec<sup>r</sup> 1885

Reg. Book.

239 on the Machinery of the S. S. "Diamond"

(Number of Visits 2)

Tonnage, Gross 1126

Built at Dundee

When built 1881-7

Ditto, Net 729

Owners Dun Gem Line S. S. Co. Port belonging to Dundee

Diameter of Cylinder 25" 50"

Engines made by W. B. Thompson When made 1881

Length of Stroke 42"

Boilers made by W. B. Thompson When made 1881

Pressure of Steam 90

If Surveyed Afloat or in Dry Dock Dry Dk

Classed 100 A1

Registered Horse Power 98

Last Survey No. 1

Port Dun

LMC. 2-85

## Particulars of Repairs and Examination S. S. No 1

(State clearly the cause of Repairs if any, and in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

The Sea Cocks & propeller examined & found satisfactory.

The Crank shaft examined & found sound.

The tail shaft down 3/16

The Cylinders, Slides, pistons, pumps & the Engines generally examined & found satisfactory.

The Main & donkey boilers examined & found in good condition.

The Main & donkey Safety Valves examined & tested under steam.

The owners state that the tail shaft will be drawn for examination early next year.

## General Observations, Opinion, and Recommendation :--

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The machinery of this vessel as far as seen is in good order & eligible in my opinion to remain as classed & to have L. M. C 12-85 recorded, when the propeller shaft has been examined,

Office or Registration Fee (per Sec. 27) £ : :  
Survey Fee (per Section 28) £ 3 : 3 : 0  
Special Damage Fee (per Section 28) £ : :  
\*Certificate (if required) £ : :  
Travelling Expenses (if chargeable) £ : :

received by me,


188

Paid See letter attached John H Heck

Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute

Assigned M. G. 2, 85



Lloyd's Register Foundation

ABNS-0199



# REPORT of SURVEY for REPAIRS, &c.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

3631, 000

It is submitted that this vessel is eligible to have the notification No. 6 12.85 recorded subject to the survey of propeller shaft in 3 months as promised by owner

D.P.

17/12/85.



© 2019  
Lloyd's Register  
Foundation