

REPORT of SURVEY for REPAIRS, &c.

No. *4067* Date of Writing Report *March 26* 18*90* Port of *Aberdeen*
 No. in Survey held at *Aberdeen* Date, First Survey *Mar 14* Last Survey *Mar 26* 18*90*
 Reg. Book. *S.S. James Hall* (No. of Visits *4*) Master *Mr. Donald*
53 on the

TONNAGE:—
 NET *184*
 GROSS *346*
 UNDER DK. *317*
 Built at *Aberdeen* By whom *Hall Russell & Co* When *1870*
 Owners *Mr. Leith, Moray, Firth S.S. Co. Ltd.* Port belonging to *Aberdeen*
 Owners' Address
 (if not already recorded in Appendix to Register Book.)
 If Surveyed Afloat or in Dry Dock *dry dk* Name of Dock *Mr dry dk* Destined Voyage *Coasting*
 Length of Poop *ft.:* of Forecastle *ft.:* of Raised Or. Deck *ft.:* Moulded Depth *ft.* ins.
 (if these particulars are not yet recorded in the Register Book.)

Classed *90 A. 11-88*

Last Survey, No. *5964* Port *Leith* *N.B. 79* *L.M.C. 11. 11-88* *S.S. Mr No 3. 12.82* *S.S. Mr No 1-86*
 (State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard
 Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials (if assigned)
 of any letters respecting this case.) as painted on Ship } in Summer *ft.* ins.
 } in Winter *ft.* ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Annual Survey*

The vessel placed in the above dry dock and the bottom examined and found in good condition and afterwards repainted. One plate on the port side in way of the fore cabin broken while entering the dry dock also one frame in way of same. The plate has been renewed and the frame doubled where broken

PRESENT CONDITION OF THE					
Decks	<i>Good</i>	Plank (Bottom) & Counter	<i>Good</i>	Ceiling	<i>Good</i>
Waterways	"	Treenails or Rivets	"	Rudder	"
Comings	"	Breasthooks & Stemson	"	Windlass & Capstan	"
Up'r Dk. Beams & Fastenings	"	Transoms, Pointers, & Crutches	"	Pumps	"
Low'r Dk. Beams & Fastenings	"	Timbers of Frame at the openings	"	Cement (if Iron Ship)	"
Planksheers	"	Ditto ditto at other places	"	Caulk'g of Bot'm, D'k, & Watrways	"
Sheerstrakes	"	Keelsons	"	Copper, or Y.M. (State if on Felt.)	"
Topsides	"	Clamps & Shelves	"	When put on	"
Wales	"				
Engine Room Skylights	"	Coal Bunker, Openings, Lids, &c	"	Scuppers	"
				Cargo & Main Hatchways	"
				Hatches	"

General Observations, Opinion as to Class, Recommendation, &c.:

This vessel so far as seen is in good and efficient condition and eligible in my opinion to remain as classed and to be noted 3-90 in the Register Book

Entry Fee (if chargeable) per Scale I., Sec. 27.	£	:	:	Fees applied for,
Office Fee (if chargeable) per Scale II., Sec. 27.	£	:	:	
Survey Fee (per Section 28)	£	:	:	18
Special on Damage, Fee (if any) (per Sec. 28)	£	:	:	Received by me,
*Certificate (if required) to be sent as per margin	£	:	:	
Travelling Expenses (if chargeable)	£	:	:	18
Second Surveyor's Fee (if any)	£	:	:	

Committee's Minute *TUES 1 APRIL 1890*
 Character assigned *90 A. 11-88*
BS 3/90

G. L. Kindmarck
 Surveyor to Lloyd's Register of British & Foreign Shipping.

