

REPORT, No.

822

FROM

Antwerp

DATE

5/3/83

ON THE

Burgemeester de Water

REMARKS OF THE CHIEF SURVEYOR.

This vessel has been built in accordance with the approved plans, excepting that the Hold Beam Stringer is not attached to the outside plating, but the compensation afforded is sufficient and it is submitted the vessel merits the favorable consideration of the Committee to be classed 100A1 as recommended.

18x 2 1/2 B



© 2018

Lloyd's Register
Foundation