

First Entry Report Belfast No 3304 on the steel
of "Star of Victoria".

It is submitted that the Report should be
returned and Mr Turpin requested to state whether
the Bilge stringer angle steels are $6\frac{1}{2} \times 4 \times \frac{16}{32}$ as given
on the Report or $6\frac{1}{2} \times 4\frac{1}{2} \times \frac{16}{32}$ as shown on the sketch of
Midship Section, and as required by the Rules.

With reference to the Freeboard marking on this
vessel, Mr Turpin should be informed that the Fresh
Water line should be $5\frac{1}{2}$ inches above the centre of the
disc and not 5 inches as stated on the Report.

Dr: 11/4/87.



© 2019

Lloyd's Register
Foundation

BEL54-0017