

Lloyd's Register of British
and Foreign Shipping.

LLOYDS REGISTER

LONDON.

REC'D 19 SEP 94

ANSR

L 6 Sept 2019

18th September 1894

The Secretary
London

Sir,

With reference to the new steamer "Ching Wo" the first entry reports upon which have been forwarded today, I beg to say that information has been received by the Builders that on the vessel's passage from here to Newport the Condenser was allowed to get hot, with the result, probably upon cooling it down, that the casting cracked from near one end at the back, the crack extending for about 22 ins. I have not been able to obtain further particulars as to the cause of the overheating as the report received by the Builders does not clearly state this. It is stated that the damage will be repaired in Newport, & the Surveyor there is being advised.

I am Sir

Your obedient servant

A. L. Jones

afp

19/9/94

of Mr Hill to
It is submitted that the
Surveyor at Newport be
requested to survey and
report upon this repair
to Mr.

28/9/94 20-9-94

WJ



© 2019

Lloyd's Register
Foundation