

(Received at London Office

BEL64-0239

The adjacent vertical stays found corroded but not to serious extent.
Safety valves examined apart & adjusted under steam to lift at 60 lbs
per sq in.

A. L. Jones

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

See moderate repairs
attached to Machinery

It is submitted that
this vessel is eligible for
RECORD + LMC 395

7979

30-3-95



© 2019

Lloyd's Register
Foundation