

Received by Chief Ship Surveyor 17. 12. 00

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME *Twin L.S. "Indian"* Report *Bel.* No. *5212*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

Nature of Survey *First entry*

It is submitted that before this case receives the consideration of the Committee, the Belfast Surveyors should be wired as follows ;—  
"Steamer Indian has cement been dispensed with inside double bottom  
"except under boilers as proposed by Owners May last wire reply".

*C. H. J.*  
*17/12/00*



© 2019

Lloyd's Register  
Foundation

*BEL 71-067*