

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book 76106 Survey held at on the Wood, Iron or Steel HOKUTAI MARU Date, First Survey Last Survey 19

Tonnage: GROSS 5220, UNDER DK 4803, NET 3818. Built at Belfast By whom Harland & Wolff Ltd When 1918

Owners Kitagawa Sangyo Kaisha Ltd. Owners' Address (if not already recorded in Appendix to Register Book). Port belonging to Osaka

Managers. Name of Dock. Destined Voyage. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Cell DBor DBa feet; uE&B feet; f feet. Total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined. Last Report, No. 2293 Port Nag.

CHARACTER: \* for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Survey (including date of N.B., if any).

+ 100 AI 9.37. + Lmc 9.37 CL 9.37. ss Mt No 3 - 2.31. ss Am No 1 - 35.

Cargo bottom not fitted in tween decks. Society's Freeboard (if assigned) as painted on Ship and now verified.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

CATEGORY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Plating	Cement or Asphalt	Oil Bunkers	Boats
Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Plating in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Frames	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchor, No. of
Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Frames	Have Watertight Doors been examined and found efficient?	Treenails	length (on board) mean diam.
Frames	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length size
Bottom Plating	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Bottom Tanks been examined internally?	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Bottom Tanks been tested?		" " at other places	Standing and Running Rigging
		Stringers, Clamps & Shelves	Sails
		Salting (State if examined.)	

### General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fee	Fees applied for
Survey Fee (per Section 20)	19
Special Damage or Repair Fee (if any) (per Sec. 20)	Received by me,
Travelling Expenses (if chargeable)	19
Second Surveyor's Fee (if any)	

Committee's Minute. Character Assigned. Surveyor to Lloyd's Register of Shipping. General Committee. Thursday 27 April 1939. Committee's decision confirmed.

19 APR 1939

\$ - Japan 4-39(-) WOF.

No Plan

Is Certificate required? If so, to be sent to

BELTZ-010A

