

Wood vessel "Ada E. Cultra", built
in the United States (date unknown).

This vessel has been nearly
rebuilt. The whole of upper planking,
ceiling, deck, beams, and frame timbers
have been removed down to the
13 feet water line: below this the
whole of the ceiling has been removed.

These parts have been replaced
with Norwegian Red pine and
Pitch pine 6 & 9 years material.

The vessel has also been salted,
and is recommended to be classed GA1

It is respectfully submitted
that it is not a case for the GA class,
but as the vessel has had a most
extensive repair, and the old
rule for Restoration has been more
than complied with, it appears to
be a case for the favorable consideration
of the Committee to assign the class
A on Restoration for 7 years viz—

6 years on account of materials
1 " for Salt
7 A—

Restored A— for 7 years from 76

"6th 4 years rest" 8/11/76 J.F.W.

As The bottom it appears has been
doubled with 3rd fir from the keel
to the 13 feet water line, but a portion
of the 1st futtocks are of fresh 6 years
material

[Signature]



© 2021

Lloyd's Register
Foundation