

Received by Chief Surveyor 15-12-99

Received from Chief Surveyor

VESSEL'S NAME Iron Bk Broughton Report Apl No. 2663

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

S.S. No. 2

Signature of Surveyor

The S.S. No. 2 has now been held, and the following repairs done (due to wear & tear) :-

1 Rudder pintle renewed & other brushed
wood main deck mostly renewed & minor
repairs. Plating has been drilled for thickness (^{see sketch.}
This 'not required by rule to be done at this survey') and in
view of surveyor's statement that the plates were drilled in
places that ~~were~~ appeared or were likely to be most wasted,
the thicknesses obtained may be considered satisfactory

It is submitted the vessel is worthy to remain classed * A1with record of Survey 12-99apl and notation of S.S.Apl No 2, 99 as recommended.* A112-99 AplSS apl No 2, 99pt ND 99.

15-12-99
© 2019 LR
C. H. P.

Lloyd's Register
Foundation

BID77-0258