

S.S. "CORNWALL".

It is submitted the Federal Steam Navigation Co. be informed that Mr. Fowling, who visited the ship when she was in dry dock at Barry, recommended as a permanent repair that a steel plate shoe, similar to the previous one, $\frac{3}{4}$ " thick, should be fitted to the sole piece of the stern frame.

W.B.

C.B. C.F.

30.1.13.



© 2021

Lloyd's Register
Foundation