

If Surveyed Afloat or in Dry Dock *in dry dock*

With reference to the "Great Britain" Report No 2696, I submit to state that listrips had been originally left open all along the upper part of Bilges, under Hold Beams, and in tween decks, and at the ends; and that the iron sides extended down over the bilges and were bolted into floors in accordance with the Rules.

For W. M. S. A.
CL492-0039

Copper or Iron.

Scarp of Keel.....N°.

Bolts thro' the Bilge and Limber Strakes....

Hold Beam

Floor Timber Bolts.....

Butt End Bolts

Deck Beam