

REPORT of SURVEY for REPAIRS, &c.

Date of Writing Report 19. When handed in at Local Office 19. Port of Dublin
No. in Reg. Book. 262/558 Survey held at Dublin Date, First Survey 10th July Last Survey 25th July 1903
on the Wood, Iron or Steel S.S. Captain McBlane Master J. Gallahan
TONNAGE:— Built at Port Glasgow By whom Murdoch & Murray When 1885 MONTH 9
GROSS 503 Owners M. Murphy Jun Port belonging to Dublin
UNDER DE. 416 Owners Address
NET 304 (if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? both Name of Dock Graving Dock Destined Voyage Crop Channel
WB=CellDBorDBa feet; uE&B feet; f feet; f
total capacity tons. FPT tons; APT tons; MT feet tons.
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 2091 Port Dublin

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.)

CHARACTER:
* for Special Survey.
Date of last Survey and of Periodical Surveys.
Year Assigned now expired.
Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1 Dub +L.M.C. 7.01
7.02 B.S. 7.02
S.S. Iron No 1.01 N.B. 3.00
S.S. Dub No 3-8.97
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Docking

Whilst in the Graving Dock, the bottoms, rudder, & all fastenings were examined & the surfaces subsequently cleaned & coated. Plating in holds cleaned & painted. Steering gear overhauled & made good.

Repairs due to wear & tear. Face angles on two web frames strengthened with plates. The position of the temporary wood bulk head in the fore hold, has been shifted aft, & now is attached to the 3rd web frame. The Hatchway is altered, as per attached sketch.

SUMMARY OF DAMAGE REPAIRS:—

	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	good	Stringers	good	Dblg. Plates under Sounding Pipes	good	Copper, or Y.M. of Wood Vessels.	
Caulking of Decks		Inner Bottom Plating		Engine Room Skylights	good	(State if on Belt.)	
Waterways		State if Tanks have been examined inside	no	Coal Bunkers, Open'gs, Lids, &c.		When put on, Month	Year
Coamings		State if Tanks now tested	no	Souppers		Boats	good
Beams & Fastenings		Bulkheads	good	Cargo Hatchways	see sketch	Masts, Yards, &c.	
Outside Plating		Ceiling		Hatches		Condition, how ascertained	from deck
Caulking of ditto		Cement or Asphalt (State which.)		Planking of Wood Vessels		(State if wedges removed)	no
Rivets		Rudder		Caulking	ditto	Sails	good
Breasthooks & Crutches	not seen	Windlass		Treenails	ditto	Equipment letter	h
Transoms		Have Pumps now been examined and found efficient?	yes	Breasthooks & Stemson	ditto	Anchors, No. of	5
Frames	good	Have Sluice Valves now been examined and found efficient?	yes	Transoms, Pointers, & Crutches ditto		Cables (State if now ranged)	no
Reverse Frames		Have Watertight Doors now been examined and found efficient?	yes	Timbers of Frame at openings ditto		" length (on board)	size stated
Floors	not seen			Ditto ditto at other places ditto		" Rule length (per Table 22)	size complete
Keelsons				Stringers, Clamps & Shelves ditto		Hawsers & Warps	good
				Salting (State if examined.) ditto		Standing & Running Rigging	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel is in a good & efficient condition & eligible in my opinion to remain as classed with record of survey 7.03 in the Register Book.

Office Fee (if chargeable) per Scale II., Sec. 27 £

Survey Fee (per Section 28) £

Special Damage or Repair Fee (if any) (per Sec. 28.) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

25/7/1903

Received by me,

29.7.03

John Macmillan

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES. 28 JUL 1903

Character Assigned

HULL CERTIFICATE
WRITTEN 13.8.03

Lloyd's Register
Foundation
DU 398-0143