

REPORT of SURVEY for REPAIRS.

No. *949* Survey held at *Glasgow* Date *7th August* 1854
 on the *Barge Comatin* Master *John Denton*
 Tonnage *353* Built at *Glasgow* When built *1839*
 By whom built _____ Owners *Wilson & Mr. Denton*
 Port belonging to *Glasgow* Destined Voyage *Sydney*
 If Surveyed Afloat or in Dry Dock *Patent Slip*

Last Survey, No. *700* Port *Glasgow* Classed *10th A. 1. S.S. 53*

REPAIRS *Three new Stanchions, Bulwarks and Rails repaired*
Put in Nine Pairs of Additional Diagonal Iron Hanging Knees
to the Hold Beams and One Pair of Rides with Side Arms
extending to below the Bilges Bolted with Iron through and
clenched; Caulked from the Sheathing up and part of
Decks and Waterways
Several new Sheets and Patches of Yellow Metal Sheathing

Present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>Good</i>
Waterways <i>do</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>2 do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>2 do</i>
Upper Deck Beams & Fastenings <i>do</i>	Timbers of the Frame <i>do</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>do</i>	Sails <i>do</i>
Planksheers <i>do</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>31 Br 1 Shw. Wedge</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>Complete & Good</i>
Topsides <i>do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do do</i>
Wales <i>do</i>	Copper <i>Yellow Metal</i> When put on <i>1853</i>	Standing & Running Rigging <i>do do</i>
Plank (Bottom) and Counter <i>When seen do</i>		

General Observations and Opinion, *Ship in good Condition fit for the safe Conveyance of*
Dry and Perishable Cargoes to and from all parts of the World and
to Continue as Classed


The Amount of Fee.....£ *2* : : : is received by me, *Wm. Denton*

Special..... : : : :

Certificate (if required) : : : :

Committee's Minute *15th August 1854*

Character assigned *A. 1 asterisk*



© 2019

Lloyd's Register
Foundation

GL 5141-0362