

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No. 2518** Survey held at **Glasgow** Date **31st July** 18 **66**
 on the Ship **"Lord Clyde"** Master **M. Martin**
 Tonnage **1010** Built at **Glasgow** When built **1864**
 By whom built **M. Menzie** Owners **A. G. Midston & Co.**
 Port belonging to **Glasgow** Destined Voyage **India**
 If Surveyed Afloat or in Dry Dock **Alex. Stephen & Son Patent Slip**

Last Survey, No. **2232** Port **Glasgow** Classed **Y.A. 1**

REPAIRS

**Gellow Metal Sheathing Shipped, Bottom Rubbed Bright
 Caulked and Sheathed with Gellow Metal on Sill to upper part of
 Males**

Present Condition of the

Decks Where Seen Good	Treenails Where Seen Good	Windlass and Capstan Good
Waterways do	Breasthooks and Stemson do	Pumps do
Comings do	Transoms, Pointers, and Crutches do	Boats do
Upper Deck Beams & Fastenings do	Timbers of the Frame at the openings do	Masts, Yards, &c. do
Lower Deck Beams & Fastenings do	Ditto Ditto at other places do	Condition, how ascertained from Examination
Planksheers do	Keelsons do	Sails Complete
Sheerstrakes do	Clamps and Shelves do	Anchors No. of 3 B & 1 Stem 2 Wedge
Topsides do	Ceiling do	Cables Complete
Wales do	Rudder do	Hawsers and Warps do
Plank (Bottom) and Counter do	Copper G. Metal When put on 1866	Standing & Running Rigging do

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

Is in good Condition Eligible to remain as classed

The Amount of Fee.....£ " : " : " is received by me.

Special..... " : " : " Accounted for

Certificate (if required) " : " : " in August

See List

Committee's Minute **7th September** 18 **1866**

Character assigned **7A**

record **MM**



© 2019

Lloyd's Register
Foundation

GLS 143-0478